



QUALITY ASSURANCE REQUIREMENTS

The vendor shall provide test reports (Non-Destructive Testing, Pressure Testing, Leak Test, visual inspections, Load Tests, etc.) signed by the vendor's Quality representative certifying that the materials furnished are in conformance with the applicable requirements of the purchase order, drawings, and/or specifications. The test reports shall reference purchase order number, specification number, contractor's name and address, and/or independent lab name and address, part number, part name, and serial number, if applicable.

Any material received without the applicable certification(s) will be processed as nonconforming material.

QUALITY NOTE 08