



## QUALITY ASSURANCE REQUIREMENTS

An ISO 17025 accredited calibration certificate shall be provided certifying that the equipment is calibrated and maintains traceability to NIST.

**Any equipment received without the certificate will be process as nonconforming material.**

## QUALITY NOTE 22